

U.S. Army, Directorate of Public Works
Planning & Environmental Branch
Attn: SELFM-PW-EV, Bldg.173
Fort Monmouth, NJ 07703

Hand delivered.
DCJ
11/15/04

TRANSMITTAL

TO:

Gregory Zalaskus,
Case Manager
NJ DEP
Bureau of Case Management
401 E. State St., 5th Fl, West Wing
PO Box 028
Trenton, NJ 08625-0028
Telephone Number: (609) 984-2065

FROM:

Douglas C. Guenther,
Environmental Protection Specialist
Phone: 732-532-0986;
Fax: 732-532-6263; DSN: 992-0986
E-mail:
Douglas.Guenther@Mail1.Monmouth.Army.mil

DATE:

November 15, 2004

URGENT FOR REVIEW PLEASE COMMENT PLEASE REPLY PLEASE RECYCLE

SUBJECT:


Document Submittal

Enclosed Please Find:

(2) Copies of the *Remedial Investigation Report, Site 108* prepared by Versar, Inc. A CD of the entire report including lab data is also provided.

Greg,

This RIR discusses the results of the site assessment and groundwater sampling at Site 108 (former UST site). No further action is requested at this site. Please forward a copy to John Prendergast.


Douglas C. Guenther