



**New Jersey Department of Environmental Protection
Site Remediation Program**

Report Certifications for RCRA GPRA 2020, CERCLA, and Federal Facility Sites

These certifications are to be used for reports submitted for RCRA GPRA 2020, CERCLA, and Federal Facility Sites. The Department has developed guidance for report certifications for RCRA GPRA 2020, CERCLA, and Federal Facility Sites under traditional oversight. The "Person Responsible for Conducting the Remediation Information and Certification" is required to be submitted with each report. For those sites that are required or opt to use a Licensed Site Remediation Professional (LSRP) the report must also be certified by the LSRP using the "Licensed Site Remediation Professional Information and Statement". For additional guidance regarding the requirement for LSRPs at RCRA GPRA 2020, CERCLA and Federal Facility Sites see http://www.nj.gov/dep/srp/srra/training/matrix/quick_ref/rcra_cercla_fed_facility_sites.pdf.

Documents:

- "Response to Comments on Building 2544/T-7 at ECP Parcel 28."

PERSON RESPONSIBLE FOR CONDUCTING THE REMEDIATION INFORMATION AND CERTIFICATION

Full Legal Name of the Person Responsible for Conducting the Remediation: William R. Colvin
 Representative First Name: William Representative Last Name: Colvin
 Title: Fort Monmouth BRAC Environmental Coordinator (BEC)
 Phone Number: (732) 380-7064 Ext: _____ Fax: _____
 Mailing Address: P.O. Box 148
 City/Town: Oceanport State: NJ Zip Code: 07757
 Email Address: william.r.colvin18.civ@mail.mil

This certification shall be signed by the person responsible for conducting the remediation who is submitting this notification in accordance with Administrative Requirements for the Remediation of Contaminated Sites rule at N.J.A.C. 7:26C-1.5(a).

I certify under penalty of law that I have personally examined and am familiar with the information submitted herein, including all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, to the best of my knowledge, I believe that the submitted information is true, accurate and complete. I am aware that there are significant civil penalties for knowingly submitting false, inaccurate or incomplete information and that I am committing a crime of the fourth degree if I make a written false statement which I do not believe to be true. I am also aware that if I knowingly direct or authorize the violation of any statute, I am personally liable for the penalties.

Signature:  Date: 9/21/2016

Name/Title: William R. Colvin, PMP, CHMM, PG
BRAC Environmental Coordinator



DEPARTMENT OF THE ARMY

OFFICE OF ASSISTANT CHIEF OF STAFF FOR INSTALLATION MANAGEMENT
U.S. ARMY FORT MONMOUTH
P.O. 148
OCEANPORT, NEW JERSEY 07757

September 21, 2016

Ms. Linda Range
New Jersey Department of Environmental Protection
Bureau of Case Management
401 East State Street
PO Box 420/Mail Code 401-05F
Trenton, NJ 08625-0028

Subject: Response to Comment on Building 2544/T-7 at ECP Parcel 28

Previous Correspondence:

1. NJDEP comment letter to the Army dated September 22, 2015, re: *Request for No Further Action at Parcel 28, Site Investigation Report Addendum, Fort Monmouth.*
2. NJDEP Approval letter to the Army dated August 25, 2016, re: *Remedial Action Type: Unrestricted Use. Scope of Remediation: Area of Concern: Former Gas Station Parcel 28, Monmouth County.*

Dear Ms. Range:

The referenced New Jersey Department of Environmental Protection (NJDEP) letters approved Unrestricted Use for ECP Parcel 28. The NJDEP's August 25, 2016 letter included the following comment concerning the alleged underground storage tank (UST) at former Building 2544/T-7:

"Note, this approval letter specifically does not include the former #2 fuel underground storage tank at Building 2544/T-7. As previously indicated, the Department cannot comment as to the absence or presence of a petroleum discharge as no evaluation has been performed."

FTMM has conducted sufficient due diligence with respect to a potential UST at former Building 2544/T-7. A 1956 historical fuel distribution system drawing was provided in Appendix O of the 2007 ECP Report showing a fuel oil tank near the 2544/T-7 location. Geophysical surveys followed by test pit trenching of anomalies were conducted in the general area. Anomalies indicative of an UST were not found at the 2544/T-7 location. Since FTMM has found no evidence of a tank or release at the 2544/T-7 location, no further evaluation was performed. We believe that the Army and NJDEP are in agreement regarding the status of Parcel 28. If you would like to discuss this further, please contact me by phone at (732) 380-7064 or by e-mail at william.r.colvin18.civ@mail.mil.

Sincerely,

William R. Colvin, PMP, PG, CHMM
BRAC Environmental Coordinator

Linda S. Range, NJDEP
Response to Comment on Building 2544/T-7 at ECP Parcel 28
September 21, 2016
Page 2 of 2

cc: Linda Range, NJDEP (e-mail and 3 hard copies)
Delight Balducci, HQDA ACSIM (e-mail)
Joseph Pearson, Calibre (e-mail)
James Moore, USACE (e-mail)
Jim Kelly, USACE (e-mail)
Cris Grill, Parsons (e-mail)