



**DEPARTMENT OF THE ARMY**  
 Headquarters, U.S. Army Garrison Fort Monmouth  
 Fort Monmouth, New Jersey 07703-5000



REPLY TO  
 ATTENTION OF

February 17, 1994

Directorate of Engineering and Housing

New Jersey Department of  
 Environmental Protection and Energy  
 Division of Responsible Party Site Remediation  
 CN 028  
 Trenton, NJ 08625 - 0028  
 ATTN: Mrs. J. DiClaudio, Case Manager

Re: Response to Correspondences dated November 23, 1993  
 pertaining to the discharge corrective action activities at:  
 UST #0091533-211 (Bldg. 208-B)  
 CASE # 93-10-21-1913-44


Dear Mrs. DiClaudio:


This is in response to the above referenced correspondence. Mr. Appleby has inspected the above referenced site and has not identified any immediate health or environmental concerns. To-Date the UST has been removed and we are awaiting the installation of a monitoring well to determine the impact to groundwater. All activities will be performed IAW all Federal and State regulations and overseen by Mr. Appleby.

I have enclosed an Underground Storage Tank Remedial Investigation Report (Preliminary), awaiting the well installation.

If the information provided in this enclosure is inadequate or you require further information with regard to any UST activities please contact Mr. Charles Appleby, Environmental Protection Specialist, at (908) 532-6224.

Sincerely,

  
 Mr. Charles Appleby  
 Engineering Technician  
 Subsurface/Closure  
 NJDEPE Cert. # 2056

  
 Mr. James Ott  
 Acting Director  
 Directorate of  
 Public Works

*DPW - Cor - w/ Regulators - UST File Copy.*