



DEPARTMENT OF THE ARMY
 HEADQUARTERS, US ARMY COMMUNICATIONS-ELECTRONICS COMMAND
 AND FORT MONMOUTH
 FORT MONMOUTH, NEW JERSEY 07703-5000

Bldg 2567
3021

REPLY TO
ATTENTION OF

11 APR 1990

Directorate of Engineering and Housing

Mr. Tom Farell
 New Jersey Department of Environmental Protection
 Bureau of Underground Storage Tanks
 CN 029
 Trenton, New Jersey 08625

Dear Mr. Farell:

Reference to your visit to Fort Monmouth on April 4, 1990, regarding three spills as reported on the State of New Jersey Department of Environmental Protection hotline. We have visited all three sites (Hospital, Charles Wood and Pinebrook Areas).

Per your recommendation, Fort Monmouth will install three monitoring wells at Hospital and Pinebrook to monitor contamination. However, Fort Monmouth received false signal at Charles Wood gas station. The false signal occurs due to malfunction of equipments attached to the pumps located inside the tank.

Please be advise that the case # 891212 1242, related to Charles Wood gas station be closed. The passive recovery of gasoline from the ground at Main Post Gas Station is still ongoing. Fort Monmouth has recovered approximately 6,500 of the 11,000 gallons. The rate of recovery has dropped from 20 gallons per day to 8 gallons per day.

Fort Monmouth appreciated your visit and your recommendations.

Sincerely,

JLB 4/11

John L. Booth
 Lieutenant Colonel, Corps of Engineers
 Director of Engineering and Housing

Enclosure

CF
 AMSCL-LG-SAA
 -JAA

CONCURRENCE				
OFFICE	NAME	INITIALS	DATE	TFL. NO.
ADHW	Eilers		4/10	23717
EV	Desai		4/10	21475
DEH	LTC Booth		4/10	23854

File copy