U.S. Army Garrison

Fort Monmouth, New Jersey

Underground Storage Tank Closure and Site Investigation Report

Charles Wood – Building 2038

NJDEP UST Registration No.: 192486-19 UST No.: 192486-19

September 2010

UNDERGROUND STORAGE TANK CLOSURE AND SITE INVESTIGATION REPORT

CHARLES WOOD – BUILDING 2038 NJDEP UST REGISTRATION NO.: 192486-19

SEPTEMBER 2010

PROJECT NO.: 10-24949

PREPARED FOR:

U.S. ARMY GARRISON, FORT MONMOUTH, NJ
DIRECTORATE OF PUBLIC WORKS
BUILDING 167
FORT MONMOUTH, NJ 07703

PREPARED BY:

TECOM-VINNELL SERVICES, INC. P.O. BOX 60 FT. MONMOUTH, NJ 07703

TABLE OF CONTENTS

EXE	CUTIV	E SUMMARY	IV						
1.0	UNDERGROUND STORAGE TANK DECOMMISSIONING ACTIVITIES								
	1.1	Overview	1						
	1.2	Site Description	1						
		1.2.1 Geological/Hydrogeological Setting	1						
	1.3	Health and Safety	5						
	1.4	Removal of Underground Storage Tank	5						
		1.4.1 General Procedures	5						
		1.4.2 Underground Storage Tank Excavation	6						
	1.5	Underground Storage Tank Decommissioning and Disposal	6						
2.0	SITE	E INVESTIGATION ACTIVITIES	7						
	2.1	Overview	7						
	2.2	Field Screening/Monitoring	7						
	2.3	Soil Sampling	7						
3.0	CON	CONCLUSIONS AND RECOMMENDATIONS							
	3.1	Soil Sampling Results	8						
	3.2	Conclusions and Recommendations	8						

TABLE OF CONTENTS (CONTINUED)

FIGURES

Figure 1 Site Location Map-topographic

Figure 2 Site Location Map

Figure 3 Soil Sampling Location Map

TABLES

Table 1 Summary of Laboratory Analysis

 Table 2
 Summary of Laboratory Analytical Results-TPH

APPENDICES

Appendix A Certifications

Appendix B UST Disposal Certificate
Appendix C Photo Documentation

Appendix D Soil Analytical Data Package

EXECUTIVE SUMMARY

UST Closure

On April 11, 2000, a fiberglass wrapped plastic underground storage tank (UST) was closed by removal in accordance with the Directorate of Public Works (DPW) UST Management Plan for the U.S. Army Garrison, Fort Monmouth, New Jersey. Installed in 1985, the tank was located adjacent to Building 2038 in Charles Wood area. UST No.: 192486-19 was a 550-gallon, FRP, No. 2 fuel oil tank. The tank with all associated piping was present at the time of removal. The tank closure was performed by TECOM-Vinnell Services, Inc. (TVS).

Site Assessment

The site assessment was performed by TVS personnel in accordance with the NJDEP *Technical Requirements for Site Remediation (N.J.A.C.* 7:26E) and the NJDEP *Field Sampling Procedures Manual.* Soils surrounding the tank were screened visually and with air monitoring instruments for evidence of contamination. Following removal, the UST was inspected for holes, of which none were found. No petroleum odors or stained soils were observed in the soils surrounding the tanks.

Closure soil samples were collected after the removal of the UST. Closure samples 2038-A and 2038-B were collected from a total of two (2) locations along the UST bottom of the excavation for the UST No.: 192486-19. Closure sample 2038-C was collected from a location along the UST piping. A duplicate of sample 2038-A was collected. All samples were analyzed for total petroleum hydrocarbons (TPH). Groundwater was not encountered in the bottom of the excavation.

Findings

The closure soil samples collected from the UST excavation associated UST No.: 192486-19 contained TPH concentrations below the NJDEP health based criterion of 10,000 milligrams per kilogram (mg/kg) for total organic contaminants (*N.J.A.C.* 7:26E and revisions dated February 3, 1994). All soil samples, including the duplicate, contained a TPH concentration of Not Detected.

Conclusions and Recommendations

Based on the closure soil sampling results, soils with TPH concentrations exceeding the NJDEP health based criterion of 10,000 mg/kg for total organic contaminants (*N.J.A.C.* 7:26E and revisions dated February 3, 1994) are not present in the former location of the UST.

No Further Action is proposed in regard to the closure and site assessment of UST No.: 192486-19 at Building 2038.

1.0 UNDERGROUND STORAGE TANK DECOMMISSIONING ACTIVITIES

1.1 OVERVIEW

One underground storage tank (UST), New Jersey Department of Environmental Protection (NJDEP) Registration No.: 192486-19 was closed at Building 2038 of the Charles Wood area at U.S. Army Garrison, Fort Monmouth, New Jersey. Refer to site location maps Figure 1 & 2. This report presents the results of the implementation of the Directorate of the Public Work's UST Management Plan, March 1996. Installed in 1985, the UST was a 550-gallon, FRP, containing No. 2 fuel oil for residential use. It was removed on April 11, 2000.

Decommissioning activities for UST No.: 192486-19 complied with all applicable federal, state and local laws and ordinances in effect at the date of decommissioning. These laws included but were not limited to: *N.J.A.C.* 7:14B-1 et seq., *N.J.A.C.* 5:23-1 et seq., and Occupational Safety and Health Administration (OSHA) 1910.146 & 1910.120. The closure and subsurface evaluation of the UST was conducted by a NJDEP licensed TVS employee.

This UST Closure and Site Investigation Report has been prepared by TVS to assist the U.S. Army Garrison-DPW in complying with the NJDEP - Underground Storage Tanks regulations. The applicable NJDEP regulations at the date of closure were the *Closure of Underground Storage Tank Systems* (*N.J.A.C.* 7:14B-9 et seq. December, 1987).

This report was prepared using information required by the *Technical Requirements for Site Remediation (N.J.A.C.* 7:26E) (*Technical Requirements*). Section 1 provides a summary of the UST decommissioning activities. Section 2 describes the site investigation activities. Conclusions and recommendations are presented in Section 3 of this report.

1.2 SITE DESCRIPTION

Building 2038 (36 & 38 Megill Circle) is located in the Charles Wood area of Fort Monmouth, as shown on Figure 1 & 2. UST No.: 192486-19 and associated piping were located adjacent to the building, as shown on Figure 3.

1.2.1 Geological/Hydrogeological Setting

The following is a description of the geological/hydrogeological setting of Bldg. 2038. Included is a description of the regional geology of the area surrounding Fort Monmouth as well as descriptions of the local geology and hydrogeology of the Charles Wood area.

Fort Monmouth lies within the Outer Coastal Plain subprovince of the New Jersey section of the Atlantic Coastal Plain physiographic province, which generally consists of a seaward-dipping wedge of unconsolidated sediments including interbedded clay, silt, sand, and gravel.

To the northwest is the boundary between the Outer and Inner Coastal Plains, marked by a line of hills extending southwest, from the Atlantic Highlands overlooking Sandy Hook Bay, to a point southeast of Freehold, New Jersey, and then across the state to the Delaware Bay. These formations of clay, silt, sand, and gravel formations were deposited on Precambrian and lower Paleozoic rocks and typically strike northeast-southwest, with a dip that ranges from 10-60 feet per mile. Coastal Plain sediments date from the Cretaceous through the Quaternary Periods and are predominantly derived from deltaic, shallow marine, and continental shelf environments.

The property is located within the outer fringe of the Atlantic Coastal Plain Physiographic Province, of New Jersey, approximately 20 miles south of Raritan Bay. This province is characterized by a wedge-shaped mass of unconsolidated to semi-consolidated marine, marginal marine and non-marine deposits of clay, silt, sand, and gravel. These sediments range in age from Cretaceous to Holocene and lie unconformably on pre-Cretaceous bedrock consisting of metamorphic schists and gneiss, with local occurrences of basalts, sandstone, and shale (Zapecza, 1984). These sediments trend northeast-southwest and dip southeast toward the Atlantic Ocean. These sediments thicken southeastward from the Piedmont-Coastal Plain Province boundary to approximately 4,500 feet near Atlantic City, New Jersey. During the Cretaceous and Tertiary time period, sediments were deposited alternately in flood plains and in marine environments during sea transgression and sea regression periods. The formations record several major transgressive/regressive cycles and contain units that are generally thicker to the southeast and reflect a deeper water environment.

Over 20 regional geologic units are present within the sediments of the Coastal Plain. Regressive, upward coarsening deposits are usually aquifers (e.g., Englishtown and Kirkwood Formations, and the Cohansey Sand) while the transgressive deposits act as confining units (e.g., the Merchantville, Marshalltown, and Navesink Formations).

Regressive upward coarsening deposits, such as Englishtown and Kirkwood Formations and the Cohansey Sand are usually aquifers, while transgressive deposits, such as the Merchantville, Marshalltown, and Navesink Formations, act as confining units. The thicknesses of these units vary greatly, ranging from several feet to several hundred feet, and thicken to the southeast.

The eastern half of the Main Post is underlain by the Red Bank Formation, ranging in thickness from 20-30 feet, while the western half is underlain by the Hornerstown Formation, ranging in thickness from 20-30 feet. The predominant formation underlying the Charles Wood Area is also the Hornerstown, with small areas of Vincentown Formation intruding in the southwest corner. Sand and gravel deposited in recent geologic times lie above these formations. Interbedded sequences of clay serve as semi-confining units for groundwater. The mineralogy ranges from quartz to glauconite.

Udorthents-Urban land is the primary classification of soils on Fort Monmouth, which have been modified by excavating or filling. Soils at the Main Post include Freehold sandy loam, Downer sandy loam, and Kresson loam. Freehold and Downer are somewhat well drained, while Kresson is a poorly drained soil.

The Charles Wood Area has sandy loams of the Freehold, Shrewsbury, and Holmdel types. Shrewsbury is a hydric soil; Kresson and Holmdel are hydric due to inclusions of Shrewsbury. Downer is not generally hydric, but can be.

Local Geology

Fort Monmouth lies in the Atlantic and Eastern Gulf Coastal Plain groundwater region and is underlain by underformed, unconsolidated to semi-consolidated sedimentary deposits. The chemistry of the water near the surface is variable with generally low dissolved solids and high iron concentrations. In areas underlain by glauconitic sediments, the water chemistry is dominated by calcium, magnesium, and iron (*e.g.* Red Bank and Tinton sands). The sediments in the vicinity of Fort Monmouth were deposited in fluvial-deltaic to nearshore environments. The water table is generally shallow at the installation; water is typically encountered at depths ranging from 2 to 9 feet below ground surface (bgs) and in certain areas fluctuates with the tidal action in Parkers and Oceanport creeks at the Main Post.

Based on the regional geologic map (Jablonski, 1968), the Cretaceous age Red Bank and Tinton Sands outcrop at the Main Post area. The Red Bank sand conformably overlies the Navesink Formation and dips to the southeast at 35 feet per mile.

The upper member (Shrewsbury) of the Red Bank sand is a yellowish-gray to reddish brown clayey, medium- to coarse-grained sand that contains abundant rock fragments, minor mica and glauconite (Jablonski). The lower member (Sandy Hook) is a dark gray to black, medium-to-fine grained sand with abundant clay, mica, and glauconite.

The Tinton sand conformably overlies the Red Bank Sand and ranges from a clayey medium to very coarse-grained feldspathic quartz and glauconite sand to a glauconitic coarse sand. The color varies from dark yellowish orange or light brown to moderate brown and from light olive to grayish olive. Glauconite may constitute 60 to 80 percent of the sand fraction in the upper part of the unit (Minard, 1969). The upper part of the Tinton is often highly oxidized and iron oxide encrusted (Minard).

"Arsenic and lead are naturally occurring in soil and can vary widely. All soils contain naturally-occurring arsenic and lead in some amount (Kabata-Pendias and Pendias, 1984). In general, the concentrations of arsenic in any particular soil are dependent upon the parent material and the soil forming processes. Because the soil forming processes are relatively consistent in New Jersey, differences in arsenic concentrations depend primarily on the soil parent material and past and present land use (Motto, Personal comm., 1997).

Because the underlying geologic materials vary widely throughout New Jersey, naturally occurring concentrations of metals in New Jersey soils also vary widely. Even though soils within a specific soil series can be similar in texture and color, the mineral and organic matter composition of soil tend to be heterogeneous. As a result, concentrations of metals in adjacent soil samples can vary substantially over distances of a few feet.

Based on a Department survey of background concentrations of metals in soil in rural and suburban areas of the state, non-agricultural soils contained 0.02 - 22.7 ppm of arsenic with an average 3.25 ppm and less than 1.2-150 ppm of lead with an average of 19.2 ppm (Fields, et al., 1993). A statistical test was conducted to determine the correlation between sand, silt and clay content of the samples and metal concentrations. Samples containing higher clay content tended to have higher concentrations of most metals, including arsenic and lead (Fields, et al., 1993).

While naturally-occurring lead concentrations have not been detected above the Department's residential soil cleanup criteria in New Jersey, elevated arsenic concentrations have been found. Higher concentrations of naturally-occurring arsenic have been specifically associated with soils containing glauconite. The US Geological Survey found arsenic concentrations generally lower than 10 ppm in sandy soils from undeveloped areas, but concentrations were as large as 40 ppm in samples containing higher clay content (Barringer, et al., 1998). Soil sampling conducted as part of site remediation activities have shown glauconite soils to commonly contain arsenic concentrations of 20-40 ppm and range as high as 260 ppm (Schick, Personal comm., 1998). The Department is currently involved in a research project with the New Jersey Geological Survey investigating metal levels in glauconite soils." *Findings and Recommendations for Remediation of Historic Pesticide Contamination, Historic Pesticide Contamination Task Force, Final Report March 1999*

Fort Monmouth has been an operational military facility for in excess of ninety (90) years; and in many areas of Charles Wood, human activities have completely transformed the topography. Currently, Fort Monmouth is conducting a correlation study to determine the relative impact of the ubiquitous glauconitic silty sands and clays and the concentrations of dissolved arsenic observed in a number of monitoring wells on the post. Upon the completion of the study, the results will be provided to NJDEP for review and comment. It is the intent of the US Army to demonstrate that the preponderance of the dissolved arsenic is a function of soil type and chemistry and is not anthropogenic in nature.

<u>Hydrogeology</u>

The water table aquifer in the Main Post area is identified as part of the "composite confining units", or minor aquifers. The minor aquifers include the Navesink formation, Red Bank Sand, Tinton Sand, Hornerstown Sand, Vincentown Formation, Manasquan Formation, Shark River Formation, Piney Point Formation, and the basal clay of the Kirkwood Formation. The Hornerstown Formation acts as an upper boundary of the Red Bank aquifer, but it might yield enough water within its outcrop to supply individual household needs. The Red Bank outcrops along the northern edges of the Installation, and contains two members, an upper sand member and a lower clayey sand member. The upper sand member functions as the aquifer and is probably present on some of the surface of the Main Post and at a shallow depth below the Charles Wood Area. The Hornerstown and Red Bank formations overlay the larger Wenonah-Mount Laurel aquifer.

Based on records of wells drilled in the Charles Wood area, water is typically encountered at depths ranging from 2 to 9 feet below ground surface (bgs). According to Jablonski, wells drilled in the Red Bank and Tinton Sands may yield 2 to 25 gallons per minute (gpm). Some local well owners have reported acidic water that requires treatment to remove iron. Acid sulfate soils are naturally occurring soils, sediments or organic substrates (e.g. peat) that are formed under waterlogged conditions. Soil and sediment materials rich in iron sulfide tend to be very dark and soft. Iron sulfides can react rapidly when they are disturbed (i.e. exposed to oxygen). Pyrite will tend to occur as more discrete crystals in soil and organic matter matrices and will react more slowly when disturbed. The oxidation of iron sulfide in the potential acid sulfate soil materials (sulfidic material) may result in the formation of actual acid sulfate soil material or sulfuric material.

These soils contain iron sulfide minerals (predominantly as the mineral pyrite) or their oxidation products. Soil horizons that contain sulfides are called 'sulfidic materials' (Isbell 1996; Soil Survey Staff 2003) and can be environmentally damaging if exposed to air by disturbance. Exposure results in the oxidation of pyrite.

1.3 HEALTH AND SAFETY

Work site health and safety hazards were minimized during all decommissioning activities. All areas which posed a vapor hazard were monitored by a qualified individual utilizing a calibrated photo-ionizer detector: Thermo Instruments Organic Vapor Monitor (OVM) – Model #580-B. The individual ascertained if the area was properly vented to render the area safe, as defined by OSHA. All work areas were properly vented to insure that there were no contaminants present in the breathing zone above permissible exposure limits (PEL's).

1.4 REMOVAL OF UNDERGROUND STORAGE TANK

1.4.1 General Procedures

- All underground utilities were marked out by the respective trade shops or utility contractor prior to excavation activities.
- All activities were carried out with great regard to safety and health and the safeguarding of the environment.
- All excavated soils were visually examined and screened with an OVM for evidence of contamination. Potentially contaminated soils were identified and logged during closure activities.

- Surface materials (i.e., asphalt, concrete, etc.) were excavated and staged separately from all soil and recycled in accordance with all applicable regulations and laws.
- An NJDEP certified Subsurface Evaluator was present during all closure and remediation activities.

1.4.2 Underground Storage Tank Excavation

During decommissioning activities, surficial soil was carefully removed to expose the UST. The tank was completely empty and contained no liquids prior to removal from the ground.

After the UST was removed from the excavation, it was staged on an impervious surface, labeled and examined for holes. The Subsurface Evaluator observed no holes in the tank during the inspection. Soils surrounding the UST were screened visually and with an OVM for evidence of contamination. Soil staining or petroleum hydrocarbons were not observed.

1.5 UNDERGROUND STORAGE TANK DECOMMISSIONING AND DISPOSAL

Subsequent to disposal, the UST was purged with air to remove vapors prior to cutting. A 4 feet by 3 feet access hole was made in the UST using a pneumatic ripper gun with a non-sparking bit. The UST was cleaned first with rubber squeeges and adsorbent material broomed on the sidewalls and bottom. The adsorbent material was then drummed and subsequently put into Ft. Monmouth's 'Oil Spill Debris' roll-off container for proper disposal. The atmosphere in and around the tank was monitored using an OVM and an Oxygen/Lower Explosive Level (LEL) meter to ensure safe working conditions during cutting and cleaning activities.

The tank was then transported by TVS for disposal in compliance with all applicable regulations and laws. The UST disposal certification, along with backfilling authorization, is included in Appendix B.

The Subsurface Evaluator labeled the UST with the following information:

- site of origin
- NJDEP UST Facility ID number
- date of removal
- size of tank
- previous contents of tank

If available, photographic documentation of the UST is included in Appendix C.

2.0 SITE INVESTIGATION ACTIVITIES

2.1 OVERVIEW

The Site Investigation was managed by U.S. Army DPW personnel. All analyses were performed and reported by Fort Monmouth Environmental Testing Laboratory, a NJDEP-certified testing laboratory. All sampling was performed by a NJDEP Certified Subsurface Evaluator according to the methods described in the NJDEP *Field Sampling Procedures Manual* (1992). Sampling frequency and parameters analyzed complied with the NJDEP document *Technical Requirements for Site Remediation*, 7:26E-3.9 (June 7, 1993) which was the applicable regulation at the date of the closure. All records of the Site Investigation activities are maintained by the Fort Monmouth DPW Environmental Office.

The following Parties participated in Closure and Site Investigation Activities.

• Ft. Monmouth Directorate of Public Works-Environmental Division

Contact Person: Joseph Fallon Phone Number: (732) 532-6223

Subsurface Evaluator: Frank Accorsi

Employer: TECOM-Vinnell Services, Inc. (TVS)

Phone Number: (732) 532-5241 NJDEP License No.: 0010042

(TVS)NJDEP License No.: US252302

• Analytical Laboratory: Fort Monmouth Environmental Testing Laboratory

Contact Person: Dan Wright Phone Number: (732) 532-4359

NJDEP Laboratory Certification No.: 13461

2.2 FIELD SCREENING/MONITORING

Field screening was performed by a NJDEP certified Subsurface Evaluator using an OVM and visual observations to identify potentially contaminated material, of which none were found.

2.3 SOIL SAMPLING

On April 11, 2000, closure soil samples were collected after the removal of the UST. Closure samples 2038-A and 2038-B were collected from a total of two (2) locations along the UST bottom of the excavation for the UST No.: 192486-19. Closure sample 2038-C was collected from a location along the UST piping. A duplicate of sample 2038-A was also collected.

Refer to soil sampling location map in Figure 3. All samples were analyzed for total petroleum hydrocarbons (TPH). Groundwater was not encountered in the excavation.

The site assessment was performed by TVS personnel in accordance with the NJDEP *Technical Requirements for Site Remediation* and the NJDEP *Field Sampling Procedures Manual*. A summary of sampling activities including parameters analyzed is provided on Table 1. The closure soil samples were collected. After collection, the samples were immediately placed on ice in a cooler and delivered to Fort Monmouth Environmental Testing Laboratory for analysis.

3.0 CONCLUSIONS AND RECOMMENDATIONS

3.1 SOIL SAMPLING RESULTS

Closure soil samples were collected from a total of three locations (which included the duplicate) on April 11, 2000 to evaluate soil conditions following removal of the UST and piping. All samples were analyzed for TPH. The closure soil sample results were compared to the NJDEP health based criterion of 10,000 mg/kg for total organic contaminants (*N.J.A.C.* 7:26D and revisions dated February 3, 1994). A summary of the analytical results and comparison to the NJDEP soil cleanup criteria is provided on Table 2. The analytical data package, including associated quality control data, is provided in Appendix D.

Closure soil samples collected on April 11, 2000 from the UST site excavation contained concentrations of TPH below the NJDEP soil cleanup criteria.


3.2 CONCLUSIONS AND RECOMMENDATIONS


The analytical results for all of closure soil samples collected from the UST closure excavation at UST No.: 192486-19 were Not Detected for total petroleum hydrocarbons.


Based on the closure soil sampling results, soils with TPH concentrations exceeding the NJDEP soil cleanup criterion for total organic contaminants of 10,000 mg/kg are not present in the location of former UST No.: 192486-19.

No Further Action is proposed in regard to the closure and site investigation of UST No.: 192486-19 at Building 2038.

FIGURES







TABLES

TABLE 1

SUMMARY OF LABORATORY ANALYSIS

FT. MONMOUTH, BUILDING 2038, UST No.: 192486-19 11 April 2000

SAMPLE ID	LABORATORY SAMPLE ID	SAMPLE DATE	SAMPLE MATRIX	ANALYTICAL PARAMETER	ANALYTICAL METHOD
2038-A	5332.01	11-Apr-00	SOIL	TPH	OQA-QAM-25
2038-В	5332.02	11-Apr-00	SOIL	TPH	OQA-QAM-25
2038-С	5332.03	11-Apr-00	SOIL	TPH	OQA-QAM-25
2038-D	5332.04	11-Apr-00	SOIL	TPH	OQA-QAM-25
Duplicate					

ABBREVIATIONS:

TPH = Total Petroleum Hydrocarbons, NJDEP Method OQA-QAM-025 (10/97)

TABLE 2

SUMMARY OF LABORATORY ANALYTICAL RESULTS

FT. MONMOUTH, BUILDING 2038, UST No.: 192486-19 11 April 2000

TOTAL PETROLEUM HYDROCARBONS

SAMPLE ID	LABORATORY	SAMPLE LOCATION	SAMPLE	MATRIX	ТРН
	SAMPLE ID		DEPTH		RESULT S
			(in feet)		mg/kg
2038-A	5332.01	WEST END	6.5-7.0	Soil	ND
2038-В	5332.02	EAST END	6.5-7.0	Soil	ND
2038-С	5332.03	PIPING	1.5-2.0	Soil	ND
2038-D	5332.04	DUPLICATE-WEST END	6.5-7.0	Soil	ND
Duplicate					

ABBREVIATIONS:

mg/kg = Milligrams Per Kilogram = parts per million

ND = Compound Not Detected

Gray shading indicates exceedance of NJDEP health based criterion of 10,000 ppm total organic contaminants

APPENDIX A

CERTIFICATIONS

(NOT AVAILABLE)

APPENDIX B UST DISPOSAL CERTIFICATE

DIRECTORATE OF PUBLIC WORKS FORT MONMOUTH, NEW JERSEY 07703

Contract Management Division

SUBJECT: PWS-007, Residential UST Removal

Contractor: TVS Inc.

RE: Backfilling of excavation,

BUILDING #: 2038 (36+38 METILL CIRCLE)

TVS Inc.

Field Supervisor, PWS-007

ATTN: Brian Finch

Building 166

Fort Monmouth, New Jersey 07703-5000

Dear Mr. Finch:

The above referenced area has been sampled and analyzed as described in the NJDEP Regulations. The results indicate levels of petroleum contamination below the NJDEP allowable limits or that the site requires further investigation outside the scope of this contract. The contractor may proceed with the backfilling of the excavation with stone to groundwater and clean fill to grade as required in the above referenced contract specification.

Regards,

Mr. Dinker Desai

Environmental Engineer

Directorate of Public Works

CC: UST file copy

DEPARTMENT OF THE ARMY



Headquarters, U.S. Army Garrison Fort Monmouth Fort Monmouth, New Jersey 07703 - 5101



REPLY TO ATTENTION OF

Directorate of Public Works

Date: 30 January, 2001

Marpal Disposal Company, Inc. P.O. Box 188
Lincroft, New Jersey 07738

Re:

Non-Hazardous Waste Disposal

Contract No. DAAB07-96-C-8252

Location: Bldg. 166, rear Roll-off container No. 2798

Size: 30 cubic yards

USTs from Bldgs: 226(2K), 227(2K), 228(2K), 2038(.5K), 2039(.5K), 2040(.5K),

2041(.5K), 2042(.5K), McGuire AFB 1507(2.5K)

Dear Sirs:

I certify that the above referenced 30 cubic yard roll-off container provided by Marpal, Inc. contains only crushed fiberglass underground storage tanks removed from residential buildings at Fort Monmouth, NJ, and one from McGuire Air Force Base. The tanks held only No. 2 heating oil. The tanks were cleaned in accordance with acceptable industry standards and NJDEP protocol and then crushed. No free liquids are present in the container.

If you should require any additional information or help at this time, please contact Mr. Dinker Desai, Environmental Protection Specialist. He can be reached at the following telephone number: (732) 532-1475.

Sincerely,

Dinker Desai

Environmental Protection Specialist

Attachments: None

APPENDIX C PHOTO DOCUMENTATION

(NOT AVAILABLE)

APPENDIX D SOIL ANALYTICAL DATA PACKAGE

FORT MONMOUTH ENVIRONMENTAL

TESTING LABORATORY

DIRECTORATE OF PUBLIC WORKS

PHONE: (732) 532-6224 FAX: (732) 532-6263 WET-CHEM - METALS - ORGANICS - FIELD SAMPLING

CERTIFICATIONS: NJDEP #13461, NYSDOH #11699



ANALYTICAL DATA REPORT Fort Monmouth Environmental Laboratory **ENVIRONMENTAL DIVISION** Fort Monmouth, New Jersey PROJECT: IJO# 100004

Bldg. 2038

Field Sample Location	Laboratory Sample ID#	Matrix	Date and Time of Collection	Date Received
2038-A West End 6.5-7.0'	5332.01	Soil	11-Apr-00 09:30	04/11/00
2038-B East End 6.5-7.0°	5332.02	Soil	11-Apr-00 10:00	04/11/00
2038-C Piping 1.5-2.0'	5332.03	Soil	11-Apr-00 09:45	04/11/00
2038-D Duplicate 6.5-7.0'	5332.04	Soil	11-Apr-00 09:30	04/11/00
Trip Blank	5332.05	Methanol	11-Apr-00	04/11/00

ANALYSIS:

FORT MONMOUTH ENVIRONMENTAL LAB TPHC, %SOLIDS

ENCLOSURE: CHAIN OF CUSTODY RESULTS

> Daniel Wright/Date Laboratory Director

4-20-00

Table of Contents

Section	Pages
Method Summary	1
Conformance/Non-Conformance	2
Chain of Custody	3
Results Summary	4
Initial Calibration Summary	5
Continuing Calibration Summary	6-9
Surrogate Results Summary	10
MS/MSD Results Summary	11
Blank Spike Summary	12
Raw Sample Data	13-22
Laboratory Deliverable Checklist	23
Laboratory Authentication Statement	24

Method Summary

NJDEP Method OQA-QAM-025-10/97

<u>Gas Chromatographic Determination of Total Petroleum Hydrocarbons in</u> Soil

Fifteen grams (15g)(wet weight) of a soil sample is added to a 125 mL acid cleaned, solvent rinsed, capped Erlenmeyer flask. 15g anhydrous sodium sulfate is added to dry sample. Surrogate standard spiking solution is then added to the flask.

Twenty five milliliters(25mL) Methylene Chloride is added to the flask and it is secured on a orbital shaker table. The agitation rate is set to 400rpm and the sample is shaken for 30 minutes. The flask is the removed from the table and the particulate matter is allowed to settle. The extract is transferred to a Teflon capped vial. A second 25mL of Methylene Chloride is added to the flask and shaken for an additional 30 minutes. The flask is again removed and allowed to settle. The extracts are combined in the vial then transferred to a 1mL autosampler vial.

The extract is then injected directly into a GC-FID for analysis. The sample is analyzed for petroleum hydrocarbons covering a range of C8-C42 including pristane and phytane. Total Petroleum Hydrocarbon concentration is determined by integrating between 5 minutes and 22 minutes. The baseline is established by starting the integration after the end of the solvent peak and stopping after the last peak.

The final concentration of Total Petroleum Hydrocarbons is calculated using percent solid, sample weight and concentration.

TPHC Conformance/Non-conformance Summary Report

1.	Method Detection Limits provided.		Yes, No, N/A
2.	Method Blank Contamination – If yes, corresponding concentrations in each b		Lud
3.	Matrix Spike Results Summary Meet C (If not met, list the sample and corresponding outside the acceptable range).		403
4.	Duplicate Results Summary Meet Crite (If not met, list the sample and corresponding falls outside the acceptable range).		¥65
′ 5.	IR Spectra submitted for standards, bla	nks and samples.	AU
6.	Chromatograms submitted for standard if GC fingerprinting was conducted.	is, blanks and samples	Yes
7.	Analysis holding time met. (If not met, list number of days exceed	ed for each sample).	yes
Add:	itional comments:		
		4-20-00	
Labo	oratory Manager	Date	

Fort Monmouth Environmental Testing Laboratory

Bldg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (732)532-4359 Fax (732)532-6263 EMail:wrightd@mail1.monmouth.army.mil

NJDEP Certification #13461 / NYDOH Certification #11699

Chain of Custody Record

The state of the s		',			 							·
Customer: Dinker Desai				100004		٠		An	alysis	Parameters		
Phone #: X21475	Location: 8106, 2038				S	*			* = Samples Kept <4°C			
()DERA (X)OMA	()DERA (X)OMA UST Assessment				UST# 192486-19				-10		Reading	
Samplers Name / Company : Frank Accorsi/TVS					Sample	#	TPHC	% SOLIDS	VOA+10		Rea	Remarks / Preservation
Lab Sample I.D.	Sample Location	Depth(H.	Date	Time	Туре	Bottles	TP	%)/\	VOA ID#	PID	Method
5332.01	2038-A. END	6,5-7,0	4-11-00	0930	SOIL	2	Х	×	X	1457	0	1CE
02	2038-8 8256	6.5-7.0		1000		2	Χ	¥	×	1458	0	
03	2038-C, PIPING	1.5-2.0		0945		2	Х	×	×	1459	0	
	2038-D, OUPLOAK	6.5-7.0		0930	7	2	X	۲	X	1460	0	
	TRIP BYANK		A	-	AQ.	,			X	1961		Y
:										<u> </u>		
								j.	<i>₹</i> 9' ∵	<u> </u>		
												·
		-										
					<u> </u>					,		
OVM	<u>I</u> sn#580U-64455,343 was ∢	alibrated with	zero air 8. v	// 745 nom l	sohutviene	read 2	47 nn	m A	920	4-11-00 FIX	ime/d	ate & initial\
			<u> </u>	1		reau _z	<u></u> PP	k /a	410	01 25% >	1000	PRATOLL
Relinquished by (signatu		ime: (1/55	Received by (signature): Comm			Comme	nents: # VO +10 ON 25% 7 4,00			i pro i	ONE	
Relinquished by (signature): Date/Time:			J. Cleylin			-	CPA ATIBL			HILLESS / CVIII .		
			Rec	eived by (signa	ature):							
<u> -</u>				<u> </u>		1	1			To 11	· ·	m1. TY 2
•	Reduced, Standard, Scre						Remar				_	ing Tools Used
Turnaround time: ()Stan	dard 2 wks, ()Rush Days	s, ()ASAP Verb	alHrs.				All san	ple poi	nts have	been GPS? XY	ES () NO () NA

Report of Analysis U.S.Army, Fort Monmouth Environmental Laboratory NJDEP Certification # 13461

Client:

U.S. Army

Project #:

5332

DPW. SELFM-PW-EV

Location:

Bldg.2038

Bldg. 173

UST Reg. #:

192486-19

Ft. Monmouth, NJ 07703

Analysis:

OQA-QAM-025

Date Received:

11-Apr-00

Matrix:

Soil

Date Extracted:

12-Apr-00

Inst. ID.:

GC TPHC INST. #1

Extraction Method:

Shake

Column Type:

RTX-5, 0.32mm ID, 30M

Analysis Complete:

13-Apr-00

Injection Volume:

1 uL

Analyst:

B.Patel

Sample	Field ID	Dilution Factor	Weight (g)	% Solid	MDL (mg/kg)	TPHC Result (mg/kg)
5332.01	2038-A	1.00	15.05	89.37	175	ND
5332.02	2038-B	1.00	15.18	89.96	172	ND
5332.03	2038-C	1.00	15.40	86.97	175	ND
5332.04	2038-D	1.00	15.38	89.01	172	ND
METHOD BLANK	TBLK378	1.00	15.00	100.00	157	ND

ND = Not Detected

MDL = Method Detection Limit

LABORATORY DELIVERABLES CHECKLIST AND NON-CONFORMANCE SUMMARY

THIS FORM MUST BE COMPLETED BY THE LABORATORY OR ENVIRONMENTAL CONSULTANT AND ACCOMPANY ALL DATA SUBMISSIONS

The following Laboratory Deliverables checklist and Non-Conformance Summary shall be included in the data submission. All deviations from the accepted methodology and procedures, of performance values outside acceptable ranges shall be summarized in the Non-Conformance Summary. The Technical Requirements for Site Remediation, effective June 7, 1993, provides further details. The document shall be bound and paginated, contain a table of contents, and all pages shall be legible. Incomplete packages will be returned or held without review until the data package is completed.

It is recommended that the analytical results summary sheets listing all targeted and non-targeted compounds with the method detection limits, practical quantitation limits, and the laboratory and/or sample numbers be included in one section of the data package <u>and</u> in the main body of the report.

1.	Cover page, Title Page listing Lab Certification #, facility name and address, & date of report submitted			
2.	Table of Contents submitted			
3.	Summary Sheets listing analytical results for all targeted and n compounds submitted	on-targeted		
4.	Document paginated and legible	· · · · · · · · · · · · · · · · · · ·		
5	Chain of Custody submitted			
6.	Samples submitted to lab within 48 hours of sample collection			
7.	Methodology Summary submitted	•		
8.	Laboratory Chronicle and Holding Time Check submitted		$\frac{\mathcal{V}}{\mathcal{A}}$	
9.	Results submitted on a dry weight basis			
10. 11.	the state of the s			
Dal	Laboratory Manager or Environmental Consultant's Signature			

*Refer to NJAC 7:26E - Appendix A, Section IV - Reduced Data Deliverables - Non-USEPA/CLP Methods for further guidance.

Laboratory Certification #13461

Laboratory Authentication Statement

I certify under penalty of law, where applicable, that this laboratory meets the Laboratory Performance Standards and Quality Control requirements specified in N.J.A.C. 7:18 and 40 CFR Part 136 for Water and Wastewater Analyses and SW-846 for Solid Waste Analysis. I have personally examined the information contained in this report and to the best of my knowledge, I believe that the submitted information is true, accurate, complete and meets the above referenced standards where applicable. I am aware that there are significant penalties for purposefully submitting falsified information, including the possibility of a fine and imprisonment.

Daniel K. Wright Laboratory Manager